

REPLACEMENT SHEET

1/55




Figure 1




Figure 7





Figure 8

REPLACEMENT SHEET

2 / 55



REPLACEMENT SHEET






Fig. 3

210

212



REPLACEMENT SHEET

4 / 55




FIG. 4

REPLACEMENT SHEET

5 / 55




Fig. 5

REPLACEMENT SHEET

6 / 55






FIG. 6


REPLACEMENT SHEET

7/55



REPLACEMENT SHEET

8 / 55



REPLACEMENT SHEET

9 / 55




Fig. 11

REPLACEMENT SHEET





Fig. 12



REPLACEMENT SHEET

11 / 55




Fig. 13




FIG. 14





FIG. 15

REPLACEMENT SHEET

14 / 55






FIG. 17




FIG. 18

REPLACEMENT SHEET

17 / 55





FIG. 19



REPLACEMENT SHEET

19 / 55




Fig. 21




Fig. 24




FIG. 22





FIG. 23


REPLACEMENT SHEET

22 / 55



REPLACEMENT SHEET

23 / 55






Figure 28

REPLACEMENT SHEET

25 / 55




Fig. 29

REPLACEMENT SHEET

26 / 55




FIG. 30a




FIG. 30b




FIG. 31

REPLACEMENT SHEET

27 / 55




Fig. 32

REPLACEMENT SHEET

28 / 55




Fig. 33




Fig. 34

REPLACEMENT SHEET

29 / 55




Fig. 35




Fig. 36




Fig. 37

REPLACEMENT SHEET

30 / 55




Fig. 38




Fig. 39




Fig. 40

REPLACEMENT SHEET

31 / 55




Fig. 41




Fig. 42

REPLACEMENT SHEET

32 / 55




Fig. 43




Fig. 44

REPLACEMENT SHEET

33/55




Figure 45

REPLACEMENT SHEET

34 / 55




Fig. 46

REPLACEMENT SHEET

35 / 55




Fig. 47

REPLACEMENT SHEET

36 / 55




FIG. 48

REPLACEMENT SHEET

37 / 55




FIG. 49

REPLACEMENT SHEET

38 / 55




FIG. 50

REPLACEMENT SHEET

39 / 55




Fig. 51

REPLACEMENT SHEET

40 / 55




FIG. 52

REPLACEMENT SHEET

41 / 55




FIG. 53

REPLACEMENT SHEET

42 / 55




Fig. 54

REPLACEMENT SHEET

43 / 55




Fig. 55

REPLACEMENT SHEET

44 / 55




Fig. 56

REPLACEMENT SHEET

45 / 55




FIG. 57

REPLACEMENT SHEET

46 / 55




FIG. 58

REPLACEMENT SHEET

47 / 55





Fig. 60



Fig. 59

REPLACEMENT SHEET



REPLACEMENT SHEET




Fig. 62

REPLACEMENT SHEET

50 / 55




Fig. 63




Fig. 65

TOP






Fig. 64

REPLACEMENT SHEET

51 / 55

Fig. 66

FRONT ELEVATION



SIDE ELEVATION

Fig. 67

REPLACEMENT SHEET

52 / 55




Fig. 68

53 / 55



REPLACEMENT SHEET

54 / 55




FIG. 70




FIG. 71